

## Technical Notification

Document number: 95-128207  
Page [1 of 2]

Date: September 2008

### **New FleetCP software, version 2.13, for the TT-3084A, TT-3086A and TT-3088A.**

#### **Subject:**

Please be informed that a new FleetCP software version, ver. 2.13 has been released.

Please be informed that this FleetCP ver. 2.13 will support the BDU SW up to ver. 1.70 for all types of Fleet systems (Sailor Fleet77, Sailor Fleet55 and Sailor Fleet33).

The new software can be downloaded from the Thrane & Thrane A/S eSupport Download Center as follows:

- 1) Enter eSupport:  
<http://extranet.thrane.com/Support/Technical%20Support.aspx>.
- 2) Select "GLOBAL SUPPORT - LOGIN"
- 3) Enter Downloads → Fleet → Software
- 4) Find and download this file "TT-3084A - TT-3086A - TT-3088A FleetCP ver. 2.13".

The file you are downloading is a ZIP-file, which you have to extract using WinZip or WinRAR.

#### **Priority:**

- **Medium:** It is recommended to apply this change / initiative to all units in stock. For units sold it is recommended to apply this change / Initiative next time the system(s) is inspected/serviced.

Continued....

## Identification:

### Points of changes since last FleetCP release (ver. 2.12b).

#### BDU:

1. Support Sailor Fleet TT-3084A, Sailor Fleet TT-3086A and Sailor Fleet TT-3088A BDU SW version 1.70 and backwards.
2. Supports the setting up of the new I/O port function, External Ringer.
3. Supports the setting up of the new Watchdog function of the Sailor Fleet TT-3084A, Sailor Fleet TT-3086A and Sailor Fleet TT-3088A system.
4. Supports the enabling and selection of the NMEA input port (external GPS) of the Sailor Fleet TT-3084A, Sailor Fleet TT-3086A and Sailor Fleet TT-3088A.
5. Bug corrections.

## Action:

### Equipment requirements.

- A TT-3084A Sailor Fleet77, TT-3086A Sailor Fleet55 or TT-3088A Sailor Fleet33.
- A PC running OS Win98, Win2000 or WinXP.
- A RS-232E (serial "straight line") cable.

### Installation procedure.

Run the Setup.exe file of the FleetCP and follow the description/directions in the pop-up windows.

Please note that if an earlier version of FleetCP is installed on the PC/Laptop, this version (FleetCP ver. 2.13) will be installed in the same folder as the previous. The FleetCP ver. 2.13 will overwrite the programs and files within the folder, except the saved Fleet Configuration Files (\*.cs1).

For additional Information please contact Thrane & Thrane A/S After Sales Service via the Thrane & Thrane A/S eSupport system

Thrane & Thrane  
After Sales Service

Author:	Date:	Checked:	Date:	Approved:	Date:
JL	15-09-2008	CKM	16-09-2008	CK	16-09-2008